

Structural Analysis – Lone Fir Cemetery Retaining Wall
April 14, 2016

Photos



Photo 1 – Existing Wall looking east



Photo 2 – Existing Wall looking west

Structural Analysis – Lone Fir Cemetery Retaining Wall
April 14, 2016



Photo 3 – Close-up of deteriorated portion



Photo 4 – Close-up of repaired portion

Structural Analysis – Lone Fir Cemetery Retaining Wall
April 14, 2016



Photo 5 – Grave site near top of wall and chain link fence